Scope of Work for Property Located at:					3543 North 13th Street				
	Property is: Single F	amily	V	Duplex	☐ Other ☐				
Date:	2/27/2014								
ake no respo	onsibility for problems discover	red after	the ins	spection da	s. The City of Milwaukee, the Redevelopment Author te, or for omissions through error or oversight. The list eral Block Grant or HOME programs.				
Exterior	Condition Report								
Location Site	Required Work Landscaping	n/a	a 🗌	Yes 🗸	Note/Comments at new parking area	\$	Cost 600.00		
	Steps/Handrails	n/a	a 🗸	Yes 🗌		\$			
	Service walks	n/a	a 🗌	Yes ✓	assumed-snow covered	\$	800.00		
	Fencing	n/a	a 🗸	Yes		\$			
	Parking	n/a	a 🗌	Yes 🗸	includes retaining wall & steps	\$	9,500.00		
	Retaining walls	n/a	a 🗸	Yes 🗌		\$			
	Other	n/a	a 🗌	Yes \square		\$			
_	Other	n/a	a 🗌	Yes 🗌		\$			
Garage	Singles: repair	n/a	a 🗌	Yes 🗌		\$			
	Shingles: Roof over existing	g n/a	a 🗌	Yes 🗌		\$			
	Shingles:Tear off & re-roof	n/a	a 🗌	Yes 🗌		\$			
	Gutters/downspouts	n/a	a 🗌	Yes 🗌		\$			
	Flashing	n/a	a 🗌	Yes 🗌		\$			
	Eaves	n/a	a 🗌	Yes 🗌		\$			
	Siding	n/a	a 🗌	Yes 🗌		\$			
	Doors	n/a	a 🗌	Yes 🗌		\$			
	Windows	n/a	a 🗌	Yes 🗌		\$			
	Slab	n/a	a 🗌	Yes 🗌		\$			
	Paint	n/a	a 🗌	Yes 🗌		\$			
	Electrical	n/a	a 🗌	Yes 🗌		\$			
	Other	n/a	a 🗌	Yes 🗌		\$			
Porches	Roof	n/a	a 🗸	Yes 🗌		\$			
	Deck-upper	n/a	a 🗸	Yes 🗌		\$			
	Decklower	n/a	a 🗌	Yes 🗸	front porch & steps	\$	1,300.00		
	Steps/handrails	n/a	a 🗸	Yes 🗌		\$			
	Ceiling	n/a	a 🗸	Yes 🗌		\$			
	Guardrails	n/a	a 🗸	Yes 🗌		\$			
	Structural	n/a	a 🗸	Yes 🗌	-	\$			
	Paint	n/a	a 🗹	Yes 🗌		\$			

n/a 🗌 Yes 🗹 **permit**

Other

85.00

\$

House

Chimney	n/a ✓ Yes		\$
Shingles: repair	n/a 🗌 Yes	includes roof repair where chimney removed	\$ 2,200.00
Shingles: Roof over existing	n/a ☑ Yes		\$
Shingles:Tear off & re-roof	n/a ☑ Yes		\$
Gutters/downspouts	n/a ✓ Yes		\$
Flashing	n/a ✓ Yes		\$
Eaves	n/a ☑ Yes		\$
Siding	n/a 🗌 Yes	▽	\$ 400.00
Storm Doors	n/a ✓ Yes		\$
Prime ("main") Doors	n/a 🗌 Yes	V	\$ 350.00
Storm Windows	n/a ☑ Yes		\$
Prime ("main") Windows	n/a ☑ Yes		\$
Paint	n/a 🗌 Yes	✓ all previously painted surfaces	\$ 2,400.00
Foundation	n/a 🗌 Yes	✓ tuckpoint	\$ 375.00
Electrical	n/a 🗌 Yes	new service	\$ 1,000.00
Other	n/a 🗌 Yes	window screens	\$ 340.00
Other	n/a 🗌 Yes	✓ basement windows (2 w/screens)	\$ 800.00
Other	n/a 🗌 Yes	✓ rear entry vestibule & steps to basement	\$ 5,400.00
Other	n/a 🗌 Yes		\$

Exterior: Estimated Cost:*

25,550.00

\$

 $[\]mbox{\ensuremath{^{\star}}}\mbox{average contracted cost.}$ Actual costs may vary. Self help will reduce the amount.

Interior Co	Ondition Report Unit: Entire unit (single family) Upper unit of duplex	✓			Lower unit of duplex Other	
Mechanical Heating	Required Work	Ш				
	Repair/replace boiler	n/a ✓	Yes			\$
	Repair radiation	n/a ✓	Yes			\$
	Repair/replace furnace	n/a	Yes	V		\$ 3,080.00
	Repair ductwork	n/a	Yes	J		\$ 700.00
	Replace thermostat	n/a	Yes	/		\$ 100.00
	Repair/replace grilles	n/a	Yes	V		\$ 100.00
Electrical	Other	n/a	Yes	V	permit	\$ 85.00
Licotrical	Repair/replace receptacles	n/a 🗌	Yes	V		\$ 1,200.00
	Repair/replace switches	n/a	Yes	/		\$ 1,200.00
	Repair/replace fixtures	n/a 🗌	Yes	V		\$ 1,200.00
	Install outlets and circuits	n/a ✓	Yes			\$
	Install outlets and circuits	n/a ✓	Yes			\$
	Install outlets and circuits	n/a ✓	Yes			\$
	Install outlets and circuits	n/a ✓	Yes			\$
	Upgrade service	n/a 🗌	Yes	V		\$ 1,749.00
	Other	n/a 🗌	Yes	/	permit	\$ 85.00
Diversities	Other	n/a 🗌	Yes			\$
Plumbing	Repair/replace kitchen sink	n/a 🗌	Yes			\$
	Repair/replace kitchen sink fauce	:n/a 🗌	Yes			\$
	Repair/replace tub	n/a 🗌	Yes			\$
	Repair/replace tub faucet	n/a	Yes			\$
	Repair/replace toilet	n/a 🗌	Yes			\$
	Repair/replace lavatory	n/a 🗌	Yes			\$
	Repair/replace lavatory faucet	n/a 🗌	Yes			\$
	Repair/replace wash tub	n/a	Yes			\$
	Repair/replace wash tub faucet	n/a	Yes			\$
	Other	n/a 🗌	Yes	V	permit	\$ 85.00
	Repair drain/waste/vent piping	n/a 🗌	Yes	√		\$ 800.00
	Repair water piping	n/a	Yes	V		\$ 800.00
	Repair/replace water heater	n/a 🗌	Yes	V		\$ 1,300.00
	Other	n/a 🗌	Yes	V	complete kitchen	\$ 1,455.00

n/a Yes complete bathroom

2,170.00

Other

						Total Exterior and Interior Cost:*	\$	49,427.00
						Interior: Estimated Cost:	\$	23,877.00
		n/a		Yes			\$	
		n/a [Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
Other	Repair defective	n/a		Yes	1		\$	1,600.00
Floors		/ [[]		Vas			Φ.	4 600 00
Stairs	Repair defective	n/a [V	Yes			\$	
	Repair/replace defective	n/a [Yes	√	Self Help	\$	248.00
Handrails	Install smoke/CO alarm: 2nd flr.	n/a		Yes	V	Self Help	\$	165.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	V	Self Help	\$	165.00
,	Install smoke/CO alarm:bsmt.	n/a [Yes	✓	Self Help	\$	55.00
Fire Safety	·							•
Paint	Repair or repl. @ defective	n/a [Yes	✓		\$	1,600.00
	Repair or repl. @ defective	n/a [Yes	J		\$	3,200.00
Walls/Ceiling		, u		103	ت	Control	Ψ	100.00
	Repair or repl. locks/latches	n/a [n/a [Yes Yes	√	Self Help	\$ \$	165.00
Doors	Repair or replace doors	n/o [Voc	7		\$	570.00
	Repair or replace sash	n/a [√	Yes			\$	
······································	Replace broken glass	n/a [J	Yes			\$	
Windows								

Inspected by: Tom Frank Date: 2/27/14

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

 $[\]ensuremath{^{\star}}\xspace$ average contracted cost. Actual costs may vary. Self help will reduce the amount.